

Vehicle Inspection Report

Plate number:	NA	Job number:	5340
Make:	ASTON MARTIN	Date:	10-11-2025
Model:	DBS	Technican	Abdul Salam
Year:	Mileage	2009	38765
Chasis no.	SCFAD06D99GE01008	Supervisor:	Danish
		Colour:	Black

Suspension & Engine

		Good ☒	Fault ☐
1	Front brake pads	X	
2	Rear brake pads	X	
3	Coolant tank with cap	X	
4	Engine turbo charge	X	
5	Engine oil	X	
6	Valve cover gasket	X	
7	Converter seal	X	
8	Water pump	X	
9	Balance rod	X	
10	Transmission oil	X	
11	Coolent level	X	
12	Radiator cap	X	
13	Fluid level	X	
14	Disc thickness	X	
15	Leaks Engine/transmission/ axles/shocks/lines)	X	
16	Tyre conditions	X	
17	Wheel alignment	X	
18	Engine main seal leak	X	
19	Turbo pipe gasket	X	

		Good ☒	Fault ☐
20	Gear mounting	X	
21	Suspension bushes	X	
22	Front lower arm	X	
23	Engine belt	X	
24	Engine Mounting		X
25	Engine belt	X	
26	Air intake pipe	X	
27	Engine cover	X	
28	V belts condition	X	
29	Alternator	X	
30	Shock absorber	X	
31	Gear converter	X	
32	Steering leaks	X	
33	Differential oil leak	X	
34	Transmission fluid level	X	
35	Steering boot	X	
36	Exhaust gasket	X	
37	Spark plugs	X	
38	Air filter	X	

Electrical & AC

		Good ☒	Fault ☐
1	Roof	X	
2	Wiper blades	X	
3	Central locking	X	
4	Dashboard	X	
5	Speakers	X	
6	Windows	X	
7	Seat adjustments	X	
8	Keys	X	

		Good ☒	Fault ☐
9	Headlight/fog lamp	X	
10	Seats	X	
11	Glove compartment	X	
12	Steering wheel	X	
13	Console	X	
14	Sunroof	X	
15	Gear converter seal leak	X	
16	Windows	X	

Bodywork

		Good ☒	Fault ☐
1	Bonnet	X	
2	Spoiler	X	
3	Front bumper	X	
4	LS fender	X	
5	LS mirror	X	
6	LS front door	X	
7	LS rear door	X	
8	LS quarter fender	X	
9	LS skirt	X	
10	LS lights	X	
11	Petrol tank	X	
12	Trunk	X	
13	Door Jambs	X	
14	Door panels	X	

		Good ☒	Fault ☐
15	HeadLight / Foglight	X	
16	Bonnet Shocks	X	
17	Rear Trunk Shocks	X	
18	RS Fender	X	
19	RS Mirror	X	
20	RS Front Door	X	
21	RS Rear Door	X	
22	RS Quarter Fender	X	
23	RS Skirt	X	
24	RS Lights	X	
25	Emblem	X	
26	Logo	X	
27	Safety Belts	X	

General comments:

- Overall car condition is good. OBD Scan report to be shared separately

Bodywork

- Body work and paint is in generally good condition with no repaints observed, minor visible scratches on the body. Carbon fibre body unable to confirm if it has been repainted
- Headlight inner film damaged (picture attached). Light is working fine
- Front hood vent mesh slightly missaligned (picture attached)
- Minor damage observed on side skirt (picture attached)

Engine, suspension and underbody

- Engine mounting observed leaking- needs full subframe removal to checking further
- Minor engine misfires 8 & 12 observed during OBD Scan- Requires troubleshooting and investigation. – Recommend to replace Spark plugs, Ignition coils and PCV valves and recheck the diagnostics
- Underneath wash required- visible marks of oil and grease observed from axle boots and oil filter
- Oil service required due in 10,000 km
- Battery needs charge and retest

Brakes/wheels/tires

- Front brake pads - 50%
- Rear brake pads- 60%
- Tires- all four are 2021 and in generally good condition

Notice / Disclaimer: I have reviewed this Pre-Purchase Inspection Report and understand that it is given solely as an "evaluation" of said vehicle's. Condition at the time and date of examination. This report is for information only and is not to be considered a recommendation for or against the purchase of the inspected vehicle. Therefore, any liability is strictly limited to the amount charged for this report. You unconditionally agree to the foregoing terms by ordering and consenting to this inspection report.







