



FIVE STAR
AUTO REPAIRING GARAGE
خمس نجوم
مرآب تصليح السيارات

TRN : 1 [REDACTED]

TAX-INVOICE

No. : IN202209-295
Date : 30/09/2022

To,

Dubai,
UAE.

Contact Person :

Staff ID :

Email ID :

TRN No :

Telephone :

Reg. No. : 6973 DXB-R Year :

Make / Model : Mercedes / S CLASS

Chassis No. : WDB1260451A526875

Odometer : 10246 Driver :

Customer Name : [REDACTED] Tel. : [REDACTED]

Vehicle Ref ID :

Estimate No./ Dt :

LPO No. / Dt :

Job. Ref. / Date : 102738

14/06/2022

S.No.	Description	Quantity	Unit Rate	Amount
-------	-------------	----------	-----------	--------

LABOUR

1	Overhauled Engine	1.00	2,000.00	2,000.00
2	Rear Both side Painting	1.00	750.00	750.00
			Total :	2,750.00

PARTS

1	Oil sump gasket	1.00	90.00	90.00
2	Gasket sump	2.00	40.00	80.00
3	Crank rear oil seal	1.00	175.00	175.00
4	Engine oil filter	1.00	40.00	40.00
5	Gasket sealant	1.00	60.00	60.00
6	Engine mounting 2x75	2.00	75.00	150.00
7	Power steering oil	1.00	90.00	90.00
8	Hose intake 2x45	2.00	45.00	90.00
9	Holder intake 8x10	8.00	10.00	80.00
10	Battery	1.00	470.00	470.00
11	Head gasket 2x90	2.00	90.00	180.00
12	Valve seal set	2.00	50.00	100.00
13	Injector rubber	1.00	300.00	300.00
14	Hose intake	1.00	65.00	65.00
15	Hose intake	1.00	60.00	60.00
16	Distributor rubber	1.00	275.00	275.00
17	Spark plug	1.00	120.00	120.00



FIVE STAR
AUTO REPAIRING GARAGE
خمسة نجوم
مرآب تصليح السيارات

TAX-INVOICE

TRN : [REDACTED]

No. : IN202209-295

Job. Ref. : 30/09/2022

Reg. No. : 6973 DXB-R

S.No.	Description	Quantity	Unit Rate	Amount
18	Plug Wire set	1.00	230.00	230.00
19	Temperature switch	1.00	90.00	90.00
20	Bonnet Sponge	1.00	170.00	170.00
21	Auto transmission accumulator	1.00	260.00	260.00
22	Petrol distributor pump asly (used	1.00	1,850.00	1,850.00
			Total :	5,025.00
GAS OIL				
1	consumables	1.00	100.00	100.00
2	Receiver drier	1.00	90.00	90.00
3	Engine oil and filter	1.00	300.00	300.00
			Total :	490.00
SUBLET				
1	A/c compressor repair	1.00	250.00	250.00
2	power steering hose repair	1.00	80.00	80.00
3	bush	1.00	45.00	45.00
4	A/c pipe repair	1.00	70.00	70.00
5	Machining charge for head seat and valve grinding , head spring lock opening Etc.	1.00	450.00	450.00
6	Pulley bush new making	1.00	60.00	60.00
7	Clean and service injectors with check	1.00	200.00	200.00
			Total :	1,155.00
OTHERS				
1	Petrol	1.00	870.00	870.00
			Total :	870.00
			GROSS TOTAL :	10,290.00

NOTE : Techn: Sajith

AED:TEN THOUSAND EIGHT HUNDRED FOUR AND 50 / 100

VAT (5%) : 514.50
Round Off (-) :
NET TOTAL : 10,804.50

Received vehicle to my entire satisfaction with all tools and accessories complete.

Bank Details: [REDACTED]

sanath.c

Customer [REDACTED]

Prepared By

We accepts no responsibility for payments made against this invoice unless cash stamp affixed and signed AND/OR evidenced by an official receipt.

Page 2 of 2

Five Star Auto Repairing Garage

Report on Job History From 01/01/2000 To 30/09/2022 (DETAIL)

Date : 30/09/2022

Document ID	Job Ref	Reg No	Job Type	Item/Job Description	Qty	Rate	Amount
November 2017							
[REDACTED]							
IN201711-270	83877	6973 DXB-R	(Makemodel:Mercedes / S CLASS Chassisno:WDB1260451A526875 Odometer:82025)				
Owner Name			[REDACTED]				
LABOUR							
				Front and rear brake oca			300.00
				Replaced silencer mountings			80.00
GAS OIL							
				Full lube service include oil and filter	1.00	250.00	250.00
				A/c gas top up	1.00	120.00	120.00
PARTS							
				Silencer rubber	2.00	60.00	120.00
						Total :	870.00
December 2017							
[REDACTED]							
IN201712-100	84086	6973 DXB-R	(Makemodel:Mercedes / S CLASS Chassisno:WDB1260451A526875 Odometer:82326)				
Owner Name			[REDACTED]				
LABOUR							
				Removed fuel distributor, replaced o rings and fuel regulator	1.00	250.00	250.00
PARTS							
				Oil seals	2.00	45.00	90.00
				Fuel regulator	1.00	820.00	820.00

Five Star Auto Repairing Garage

Report on Job History From 01/01/2000 To 30/09/2022 (DETAIL)

Date : 30/09/2022

Document ID	Job Ref	Reg No	Job Type	Item/Job Description	Qty	Rate	Amount
						Total :	1,160.00

November 2018

[REDACTED]

IN201811-95 88667 6973 DXB-R (Makemodel:Mercedes / S CLASS Chassisno:WDB1260451A526875 Odometer:87416)

Owner Name [REDACTED]

LABOUR

Replaced wiper blade 1.00

PARTS

Wiper blade 1.00 250.00 250.00

Total : 250.00

February 2019

[REDACTED]

IN201902-207 89956 6973 DXB-R (Makemodel:Mercedes / S CLASS Chassisno:WDB1260451A526875 Odometer:435207)

Owner Name : [REDACTED]

LABOUR

Replaced battery 50.00

PARTS

Battery 1.00 700.00 700.00

Total : 750.00

Discount : 35.71 Net : 750.00

Five Star Auto Repairing Garage

Report on Job History From 01/01/2000 To 30/09/2022 (DETAIL)

Date : 30/09/2022

Document ID	Job Ref	Reg No	Job Type	Item/Job Description	Qty	Rate	Amount
May 2019							
IN201905-75	90667	6973 DXB-R	(Makemodel:Mercedes / S CLASS Chassisno:WDB1260451A526875 Odometer:89802)				
Owner Name							
LABOUR							
				Removed trasnmission , crank rear oil seal and converter oil seal			950.00
				Removed propellor shaft replaced joint coupling and centre bearing			300.00
				Removed reapiir and refix power steering pump			350.00
				Remove repair and refix hydrolic pump			350.00
				Replaced engine oil pan hasket			150.00
				Coolingsystem flushing , replace radiator top and bottom hose and coolent filled			180.00
PARTS							
				Spark plug	8.00	35.00	280.00
				Prop shaft support	1.00	100.00	100.00
				Oil pan gasket	1.00	90.00	90.00
				Bearing shaft	1.00	100.00	100.00
				Oil seal	1.00	140.00	140.00
				Air filter	1.00	115.00	115.00
				Steering damper	1.00	145.00	145.00
				Gasket crank seal	1.00	200.00	200.00
				Gasket box kit	1.00	275.00	275.00
				Thermostat	1.00	95.00	95.00
				Radiator top hose	1.00	70.00	70.00

Five Star Auto Repairing Garage

Report on Job History From 01/01/2000 To 30/09/2022 (DETAIL)

Date : 30/09/2022

Document ID	Job Ref	Reg No	Job Type	Item/Job Description	Qty	Rate	Amount
				Radiator bottom hose	1.00	120.00	120.00
				Damping pad	2.00	65.00	130.00
				Gear Lever Bushing	2.00	30.00	60.00
				Hose clip	4.00	5.00	20.00
				JOint coupling	2.00	145.00	290.00
				Sensor, Coolant Level	1.00	40.00	40.00
				Coolant Tank	1.00	145.00	145.00
				Belt	1.00	50.00	50.00
				Belt	1.00	50.00	50.00
				Belt	1.00	50.00	50.00
				Belt	1.00	60.00	60.00
				At pan gasket	1.00	60.00	60.00
			GAS OIL				
				Full lube service	1.00	200.00	200.00
				flush and replace trasnmission oil	1.00	350.00	350.00
			SUBLET				
				Machining charges for propellor shaft check up	1.00	150.00	150.00
			OTHERS				
				Consumables	1.00	100.00	100.00
						Total :	5,765.00
					Discount : 0.71	Net :	6,052.50

August 2019

Five Star Auto Repairing Garage

Report on Job History From 01/01/2000 To 30/09/2022 (DETAIL)

Date : 30/09/2022

Document ID	Job Ref	Reg No	Job Type	Item/Job Description	Qty	Rate	Amount
IN201908-90	92205	6973 DXB-R	(Makemodel:Mercedes / S CLASS Chassisno:WDB1260451A526875 Odometer:90577)				
Owner Name :							
			LABOUR				
				Removed propeller shaft, replaced propeller shaft joint coupling, balanced and refixed			
			GAS OIL				
				A/c. gas top up	1.00	150.00	150.00
			SUBLET				
				Balancing charge	1.00	850.00	850.00
			PARTS				
				Joint coupling	2.00	495.00	990.00
						Total :	1,990.00

September 2019

IN201909-253	92773	6973 DXB-R	(Makemodel:Mercedes / S CLASS Chassisno:WDB1260451A526875 Odometer:91095)				
Owner Name							
			LABOUR				
				Removed rear both shock absorber, made bushes and refixed	1.00	500.00	500.00
			SUBLET				
				Shock absorber repair	2.00	200.00	400.00
				Bush new making 4@100	4.00	100.00	400.00
			PARTS				

Five Star Auto Repairing Garage

Report on Job History From 01/01/2000 To 30/09/2022 (DETAIL)

Date : 30/09/2022

Document ID	Job Ref	Reg No	Job Type	Item/Job Description	Qty	Rate	Amount
				Hydraulic oil	1.00	80.00	80.00
Total :							1,380.00

October 2019

[REDACTED]

IN201910-109 93039 6973 DXB-R (Makemodel:Mercedes / S CLASS Chassisno:WDB1260451A526875 Odometer:91397)

Owner Name [REDACTED]

LABOUR

Replaced rear Lhs suspension Accumulator 1.00

PARTS

Accumulator 1.00 935.00 935.00

GAS OIL

Power steering fluid 1.00 60.00 60.00

Total : 995.00

March 2020

OMAR ABBAS

IN202003-13 94629 6973 DXB-R (Makemodel:Mercedes / S CLASS Chassisno:WDB1260451A526875 Odometer:92896)

Owner Name [REDACTED]

LABOUR

Removed transmission assy , replaced crank rear oil seal and converter oil seal 1,300.00

Five Star Auto Repairing Garage

Report on Job History From 01/01/2000 To 30/09/2022 (DETAIL)

Date : 30/09/2022

Document ID	Job Ref	Reg No	Job Type	Item/Job Description	Qty	Rate	Amount
				Replaced engine oil pan gasket			700.00
				Replaced valve cover gasket			400.00
				Replaced trasnmission oil pan gasket			200.00
				Replaced radiator assy			250.00
			GAS OIL				
				Full lube service	1.00	300.00	300.00
			SUBLET				
				Steam wash	1.00	150.00	150.00
			PARTS				
				Gear converter oil seal	1.00	105.00	105.00
				Gasket	1.00	45.00	45.00
				Gasket	1.00	45.00	45.00
				AT Gakset	1.00	50.00	50.00
				Radiator top hose	1.00	65.00	65.00
				Thermostat with gasket	1.00	80.00	80.00
				AT Filter	1.00	65.00	65.00
				Oil pan gasket	1.00	135.00	135.00
				Oil Pan Gasket	1.00	135.00	135.00
				Oil Seal	1.00	145.00	145.00
				Radiator assy	1.00	930.00	930.00
				Gasket silicone	1.00	120.00	120.00
				Connetor o ring	1.00	45.00	45.00
				Hose clips	3.00	5.00	15.00
			GAS OIL				

Five Star Auto Repairing Garage

Report on Job History From 01/01/2000 To 30/09/2022 (DETAIL)

Date : 30/09/2022

Document ID	Job Ref	Reg No	Job Type	Item/Job Description	Qty	Rate	Amount
				Coolant	4.00	30.00	120.00
				ATF oil	9.00	45.00	405.00
			OTHERS				
				Consumables	1.00	80.00	80.00
						Total :	5,885.00

[REDACTED]

IN202003-225 94979 6973 DXB-R (Makemodel:Mercedes / S CLASS Chassisno:WDB1260451A526875 Odometer:93420)
Owner Name [REDACTED]

PARTS

Transmission oil dipstick	1.00	180.95	180.95
		Total :	180.95

March 2021

[REDACTED]

IN202103-13 98003 6973 DXB-R (Makemodel:Mercedes / S CLASS Chassisno:WDB1260451A526875 Odometer:97634)
Owner Name [REDACTED]

LABOUR

Lowering front rh suspension			350.00
Front rh hub servicing and replaced grease cap set			200.00

SUBLET

Tyres	4.00	300.00	1,200.00
-------	------	--------	----------

Five Star Auto Repairing Garage

Report on Job History From 01/01/2000 To 30/09/2022 (DETAIL)

Date : 30/09/2022

Document ID	Job Ref	Reg No	Job Type	Item/Job Description	Qty	Rate	Amount
			PARTS				
				Hub grease cap	1.00	120.00	120.00
			OTHERS				
				Consumables	1.00	30.00	30.00
			SUBLET				
				Wheel allignment	1.00	300.00	300.00
Total :							2,200.00

[REDACTED]

IN202103-158 98192 6973 DXB-R (Makemodel:Mercedes / S CLASS Chassisno:WDB1260451A526875 Odometer:)
Owner Name : [REDACTED]

PARTS

Wheel cap 2@50 2.00 50.00 100.00

Total : 100.00

Discount : 4.76 Net : 100.00

[REDACTED]

IN202103-37 98058 6973 DXB-R (Makemodel:Mercedes / S CLASS Chassisno:WDB1260451A526875 Odometer:97800)
Owner Name : [REDACTED]

LABOUR

Replaced front Rhs wheel bearing 1.00

PARTS

Wheel bearing (130+120) 1.00 250.00 250.00

Five Star Auto Repairing Garage

Report on Job History From 01/01/2000 To 30/09/2022 (DETAIL)

Date : 30/09/2022

Document ID	Job Ref	Reg No	Job Type	Item/Job Description	Qty	Rate	Amount
						Total :	250.00

June 2021

IN202106-71 98727 6973 DXB-R (Makemodel:Mercedes / S CLASS Chassisno:WDB1260451A526875 Odometer:98658)
Owner Name

LABOUR

Overhauling steering box for oil leakage			850.00
Replaced rear lh wheel bearing			250.00
Removed and replaced ignition key set			450.00

PARTS

Ignition key	1.00	120.00	120.00
Cover	1.00	100.00	100.00
Ignition coil	1.00	155.00	155.00
Steering box kit	1.00	410.00	410.00
Wheel bearing	1.00	250.00	250.00

GAS OIL

Power steering oil	1.00	40.00	40.00
Hydrolic oil	1.00	45.00	45.00

SUBLET

Repaired key barrel	1.00	350.00	350.00
---------------------	------	--------	--------

OTHERS

Petrol	1.00	80.00	80.00
Consumable	1.00	60.00	60.00

Five Star Auto Repairing Garage

Report on Job History From 01/01/2000 To 30/09/2022 (DETAIL)

Date : 30/09/2022

Document ID	Job Ref	Reg No	Job Type	Item/Job Description	Qty	Rate	Amount
						Total :	3,160.00

October 2021



IN202110-74 99512 6973 DXB-R (Makemodel:Mercedes / S CLASS Chassisno:WDB1260451A526875 Odometer:99643)

Owner Name :OMAR ABBAS

LABOUR

Replaced fuel guage 250.00

PARTS

Fuel guage 1.00 970.00 970.00

Rad cap 1.00 50.00 50.00

SUBLET

Towing charge 1.00 130.00 130.00

Total : 1,400.00

1990 MERCEDES-BENZ 560 SEC (126.045)

**General Data**

FIN	WDB1260451A526875
Model	560 SEC
Engine	117968 12 081624
Transmission	722350 03 331453
Order Number	0 0 839 50176
Order Location	JAPAN
Interior	LEATHER - BEIGE (265)
Paint 1	SMOKE SILVER METALLIC (702U)
Approx. Build Date	1990-01

Code Description

253	RADIO MB - EXQUISIT - JAPAN
442	AIRBAG IN STEERING WHEEL
498	VERSION FOR JAPAN
524	PAINTWORK - PRESERVATION
581	AUTOMATIC CLIMATE CONTROL
592	HEAT-INSULATING GLASS, ALL-AROUND, HEATED REAR WINDOW PANE, BAND FILTER
613	HEADLAMP LEFT-HAND TRAFFIC
800	CHANGE OF MODEL YEAR, THE LAST FIGURE SHOWING THE NEW MODEL YEAR
873	SEAT HEATER FOR LEFT AND RIGHT FRONT SEATS